

Using a Fumehood Pre-use Checks

CHECK

Wear appropriate PPE eg gloves and goggles (the following chart and COSHH Assessment will help), with gloves replaced regularly.

Remember, different glove thicknesses are needed dependent on what you are doing, eg, thicker gloves or material type required when handling concentrated acids / bases.

Housekeeping

Good housekeeping plays a significant part in a